
## **INSTALLATION GUIDE** EOL Zenith Wiring Panel

Items needed for the installation. All items from B to E are included in the box together with the Wiring Panel.



Avda. Anselmo Clavé nº 37-45 - 50004, Zaragoza - Spain Tel. **(+34) 976 221 789** support@kintech-engineering.com www.kintech-engineering.com




Identify the lower screws holding the data logger. (1)




(4)


(2) Detach the data logger and use those lower screws (M5x20) to install the metallic holder.




Mount the interconnection boards to the data logger. (3) Digital Input 1 and Digital Input 2 terminals are free.



5 Place the two rivets on the Wiring Panel to secur it to the metallic holder.





Slide the Wiring Panel onto the metallic holder until

the interconnection boards.

the black connector of the Wiring Panel is inserted to

(6)

Screw the separators from the Wiring Panel to the metallic holder.

	BAT + SV (1) ANE - ANE 6 GND		BAT + SV [2] ANE - ANE S GND		BAT + 5V [3] ANE - ANE 4 GND		BAT + SV [3] ANE - ANE 3 GND		BAT + SV [2] ANE - ANE 2 GND		BAT + 5V [1] ANE - GND GND
→	$\bigotimes$	•	•	•	•	•	•	•	•	•	•



